



Round Holes


A FEW OF OUR PERFORATIONS - (holes at actual size)




1/16" @ 1/8"
STAGGERED
Open area . . . 22.5%




.078 @ 1/8"
STAGGERED
Open area . . . 36%




3/32" @ 5/32"
STAGGERED
Open area . . . 32%




3/32" @ 3/16"
STAGGERED
Open area . . . 23%




1/8" @ 3/16"
STAGGERED
Open area . . . 40%




1/8" @ 1/4"
STAGGERED
Open area . . . 23%




5/32" @ 7/32"
STAGGERED
Open area . . . 46%




3/16" @ 1/4"
STAGGERED
Open area . . . 51%




3/16" @ 5/16"
STAGGERED
Open area . . . 33%



1/4" @ 5/16"
STAGGERED
Open area . . . 58%




1/4" @ 3/8"
STAGGERED
Open area . . . 40%




3/8" @ 9/16"
STAGGERED
Open area . . . 40%



7/16" @ 9/16"
STAGGERED
Open area . . . 51%



1/2" @ 11/16"
STAGGERED
Open area . . . 47%



1/2" @ 3/4"
STAGGERED
Open area . . . 40%



3/4" @ 1"
STAGGERED
Open area . . . 51%



1" @ 1-1/4"
STAGGERED
Open area . . . 58%